

Field Note Record

| Contract No. Station 9214 Project Limits | | Mile/Line: | | C/S | C/S | | |
|---|--------|----------------------|------|---------------------|---------|--|--|
| | | MP 102.55 & MP 86.25 | | | | | |
| Staked by | Date | Work Started Date | | Work Completed Date | | | |
| N/A | | 6/14/2019 | | | | | |
| Calculated by | / Date | Checked by | Date | Inspector | Date | | |
| Todd Dellinger | | E. Knudson | | Shawn Glass | 6/28/19 | | |
| 6/28/2019 | | 7/3/2019 | | | | | |

FURTHER DECK PREPARATION - EXIST. REPAIR MATL. 90/154N BID ITEM #33 UNIT: S.F.

GROUP 3

BRIDGE: 154N SEQUENCE PASS #1

Total = 1050.0 S.F.

SMALL AREAS FIELD MEASURED WITH A STEEL TAPE MEASURE BY INSPECTOR AND AGREED UPON BY GRAHAM.

SEE ATTACHED BACKUP FOR THE MEASURED CHIPPED AREAS.

| Item Nui | m Material Brand Name/Model Type | Man | Manufacturer | | Brand Name/Mo | Brand Name/Model Type | | PL Appr/A Code | cc Bas | Basis of Accept | |
|-------------|--|-----|-----------------------|------|------------------|--------------------------|----|-------------------|--------------|-----------------|-------------|
| | | | | | | | | | / | | |
| Item Num | Item Description | Grp | Date Work Complete | Unit | Quantity | Ledger Entry No | | sted By Date | Che Init. | cked By Date | Est. No. |
| 0033 | FURTHER DECK PREPARATION-EXIST. REPAIR MATL. 90/154N | 3 | 6/30/2019 | S.F. | 1,050.0 | 519 | EK | 07/03/19 | | | 14 |

Attachments



DOT Form IP 422-635ER EF Revised 4/2009